


SPARE PARTS CATALOGUE
: MCCULLOCH

Spare Parts List

SPARE PARTS LIST

REPAIR PARTS

TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
BELT GUARD AND PULLEY ASSEMBLY




belt_guard_LCT_1

PXM_REF	PXM_PARTNO	DESCRIPTION
1	823230506	VIS
2	532130812	POULIE
3	532086777	VIS
4	874770508	BOULON
5	817490440	BOULON
6	532422920	ÉCRAN
7	532170488	VIS
8	532139155	RONDELLE D'ESPACEMENT
9	532432928	PROTECTEUR
10	532109227	COUSSINET
11	532009484	COLLIER DE SERRAGE
12	532009180	COURROIE
13	812000028	COLLIER DE SERRAGE
14	532151223	DISQUE
16	812000036	BAGUE DE RETENUE
17	873350600	ÉCROU
18	532161806	POULIE
19	532175377	ARM.IDLER WELDMENT
20	874760620	BOULON
21	532106968	ARBRE
25	873350500	ÉCROU

forêtjardin.com


REPAIR PARTS

TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
DECALS



PXM_REF	PXM_PARTNO	DESCRIPTION
1	532423884	DECAL
2	532432771	DECAL
4	532432770	DECAL
5	532137539	DECAL
6	532120431	DECAL
8	532162215	DECAL
11	532120075	DECAL
12	532432769	DECAL

forretjardin.com




Service Kit Breakdown

PXM_REF	PXM_PARTNO	DESCRIPTION
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
23		
24		
25	532420600	GOVERNOR
26		
27		
28		
29		
30		
31		
32		
34		
36		
37		

REPAIR PARTS


TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
HANDLE ASSEMBLY



PXM_REF	PXM_PARTNO	DESCRIPTION	PXM_REMARK
1	532137118	TABLEAU DE BORD	137118
3	532165787	POIGNÉE	
12	898000129	ÉCROU	
13	872010506	BOULON	
14	532181476	PANNEAU	
19	532188532	COMMANDE	
20	532188555	STYLO	
29	812000059	BAGUE DE RETENUE	
35	872010520	BOULON	
36	873970500	ÉCROU	
38	532431332	POIGNEE COMPLÈTE	
39	532181580	COLLIER DE SERRAGE	

REPAIR PARTS

TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
TINE ASSEMBLY




PXM_REF	PXM_PARTNO	DESCRIPTION	PXM_REMARK
6	532004929	PIN RETAINING SCREW	
1	532156926	LAME	RH
2	532003146	COLLIER DE SERRAGE	
3	532156924	LAME	RH
4	532156923	LAME	LH
5	532156925	LAME	LH

for

etjardin.com

REPAIR PARTS

TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
TRANSMISSION




transmission_LCT_1

PXM_REF	PXM_PARTNO	DESCRIPTION	PXM_REMARK
1	874760524	BOULON	
2	874780652	BOULON	
3	819131311	RONDELLE	
5	873900600	ÉCROU	
6	532432919	ÉCRAN	
7	532188195	SUPPORT	RH
8	532165834	BRKT.ENGINE.LH	LH
11	532187912	BOULON	
12	532151222	TRANSMISSION	
14	532009173	RONDELLE D'ESPACEMENT	
15	873970500	ÉCROU	
16	819091412	RONDELLE	
17	819092016	RONDELLE	
18	810040400	RONDELLE	
19	874610412	BOULON	
20	000000000	W/O DESCRIPTION	Engine LCT PLMHK14600124P-BPQE2

REPAIR PARTS

TILLER - MODEL NO. MC900 (96083000400), PRODUCT NO. 960 83 00-04
WHEEL AND DEPTH STAKE ASSEMBLY



PXM_REF	PXM_PARTNO	DESCRIPTION	PXM_REMARK
1	532009194	PIN RETAINING SCREW	
2	874760520	BOULON	
3	874760512	BOULON	
4	873220500	ÉCROU	
5	810040500	RONDELLE	
6	873800600	ÉCROU	
7	532004921	RESSORT	
8	532001952	SUPPORT	RH
9	532122233	TAIL-SKID	
10	532000326	PIN RETAINING SCREW	
11	874780628	BOULON	
13	532001951	SUPPORT. L.	LH
15	532005388	RESSORT	
16	532121117	BOULON	
17	532406155	ROUE	
19	532009190	SUPPORT	
20	873680600	ÉCROU	
21	874760516	BOULON	
22	873800500	LOCK NUT	
24	873970500	ÉCROU	
25	819171416	RONDELLE	